Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization Audit Name: MCNAIRY

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0420

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE

Fax:

Henderson, TN

Email Address:

Agency Contact: Murley, Rickey

Work Phone: Cell Phone: Email Address:

Company Name & License Number.	
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-645-4208

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0420

Work Order Name:

Version 8.5.0

Report Run On: 5/25/2010

Measures

	Measure 1 Infilt	ration Redctn			Componen	ts		İ	nspected
C	Comment							# d = \$	
44	88 a familia III a familia	D = = = 1	l I m i den	04.	Estimated	Total	04.	Actual Unit Cost	Total
#	Material / Labor	Description / Comment	Units	Qty 1	Unit Cost	Total	Qty	Omi Cost	iOtai
1	Construction Materials/Hardwar e	Seal ceiling in closet by breaker box, Repair ceiling in hall, Seal master bedrrom closet ansd seal crown molding in bedroom, Seal ceiling in middle bedroom	Each	1					
2	Labor	Labor	Hour			7			
3	Construction Materials/Hardwar e	Ceiling to wall in bathroom, Seal pipes under vanity and wall Seal crown molding and ceiling in living room, Move D2 to interior door and seal off laundry room from junk room	Each	1		recent			
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Weather-strip door from kitchen to laundry room , Seal laundry room ceiling and corners, Seal crown molding in kitchen	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Repair hole in wall behinf frig and ceiling and floor. Repair hole under sink by cook stove and pipes under sink, Reapir ceiling in den, Seal fllor to wall, Seal wall behind chair. Seal AC on west wall, Seal window on corner N6 window	Each	1					
8	Labor	Labor	Hour						
9	Construction Materials/Hardwar e	Replace broken sash on N1 window, Replace broken pane on S4 window	Each	1			A Account of the control of the cont		

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID: Alt. Client ID: 16016SW-0420

Work Order Name:

Report Run On: 5/25/2010

Version 8.5.0 Page 2 of 6

10 Labor	Labor	Hour					The state of the s	
Other Detail	p		-q	_			,	
]		
76.								THE STATE OF THE S
			Measur	re Sub Total:			Sub Total:	
Field Notes:		THE RESIDENCE OF THE PARTY OF T						
							AND	
	DWH Pipe Insulation			Compone	nts		•	Inspected
Comment				Estimate	d		Actual	
# Material / Labo	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1			1		
2 Labor	Lohor	Each	1			[A TO
	Laboi	Laur	•					and a second contract of the second contract
Other Detail]	1				
	the best of the second				-			
The second secon								
			Measure	e Sub Total:			Sud Lotal: 📗	
2 Labor Other Detail	Labor	Each	1	Sub Total:			Sub Total:	MA (MA) (MA) (MA) (MA) (MA) (MA) (MA) (M

	Measure 3 DWI	H Tank Insulation			Componen	ts			nspected
Comment					Estimated	1		Actual	L
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1	Tay Annual Tay				
2	Labor	Labor	Each	1		777771.1. 7			
(Other Detail				og yr occupants on the common particular				
	And the state of t		Toward the refusion for the transformation of the second			and a state of the control of the co			
				Measur	re Sub Total:	TO THE REST OF STATE OF THE STA	5	Sub Total:	
	Field Notes:								
	Measure 4 Attic	: Ins. R-30			Component	fe A1			nspected
	omment	11101.11.00			oomponom.				
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1173	ALCOHOLOGICA DE LA				
2	Labor	Labor	Hour	1173					
3	Construction	Install attic acccess	Each	1					
	Materials/Hardwar e	cover							
1	Labor	l abou	Hour						
		Labor	noui						PERFECTION AND ADMINISTRATION AN
O	ther Detail							}	
_				Moscur	e Sub Total:		l	ub Total:	
1	Field Notes			ricasure	a Sub Total,			40 / Otu	
	Field Notes:								
	The state of the s	TAR. L. A.						MINE ARA A	

Client Name: Client ID:

Alt. Client ID: 16016SW-0420

Work Order (Bid Form)

Work Order Name Report Run On: 5/25/2010 DOE Weatherization Assistant Version 8.5.0

Page 4 of 6

į	Measure 5 CO	Monitor is Needed			Componer	nts			Inspecte
C	comment								
				,	Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
					34			4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		**************************************	C. v. co. anno annoma management	Measur	e Sub Total:	F. Course distance of the second		Sub Total:	
-	Field Notes:	SPACE A CO. CONTRACTOR SERVICE SERVICE (CA. Material Service Standard Service	e no meno una militarramana della con hi i di ini di edic						
	Measura 6 Fiv A	uny Other Heating Syste	om Drohl	om	Componen				Inspected
		any Other Heating Syste				ion senso	or	Actual	Inspected
C					-	ion senso	or Qty	Actual Unit Cost	Inspected
C:	omment Remove	non-ventd heaters that c	do not hav	/e a ox	ygen depleti Estimated	ion senso	man annua Abbara A. F. and Wash And Art of		
<i>C</i> (#	omment Remove Material / Labor Health and Safety	non-ventd heaters that of Description / Comment Direct Vent 35-40 KBTU	do not hav <i>Unit</i> s	∕e a ox Qty	ygen depleti Estimated	ion senso	man annua Abbara A. F. and Wash And Art of		
C i # 1	omment Remove Material / Labor Health and Safety Items	non-ventd heaters that of Description / Comment Direct Vent 35-40 KBTU Natural Gas Heater	do not hav <i>Units</i> Each	/e a ox Qty 1	ygen depleti Estimated	ion senso	man annua Abbara A. F. and Wash And Art of		
C i # 1	omment Remove Material / Labor Health and Safety Items Labor	non-ventd heaters that of Description / Comment Direct Vent 35-40 KBTU Natural Gas Heater	do not hav <i>Units</i> Each	/e a ox Qty 1	ygen depleti Estimated	ion senso	man annua Abbara A. F. and Wash And Art of		
C i # 1	omment Remove Material / Labor Health and Safety Items Labor	non-ventd heaters that of Description / Comment Direct Vent 35-40 KBTU Natural Gas Heater	do not hav <i>Units</i> Each	/e a ox Qty 1	ygen depleti Estimated	ion senso	man annua Abbara A. F. and Wash And Art of		
C i # 1	omment Remove Material / Labor Health and Safety Items Labor	non-ventd heaters that of Description / Comment Direct Vent 35-40 KBTU Natural Gas Heater	Units Each Hour	Qty 1	ygen depleti Estimated	ion senso	Qty		

	Measure 7 PressureRelief Piping Needed				Componen		Inspected		
C	Comment								
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail								
		TOTAL OF THE PROPERTY OF THE P							
				Measur	e Sub Total:		5	Sub Total:	
	Field Notes:							The state of the s	
-									
									-
1							FF F-Filming and address to the state of		
			Work Or	der Gra	nd Total:	homeon problems	Grand	d Total:	

Alt. Client ID: 16016SW-0420

Page 6 of 6